

Certified, Filed and or Recorded on
May 06, 2008 AT 01:24PM

Signed: [Signature]
MARILYN J NOVAK G V
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 9, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 2/9/07 found a 1/2" PIPE LAPPED 10918
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed an _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock Date 06 May 2008 License No. 19552

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Benton County Surveyor's Office
Jerome C. Wittstock, County Surveyor
Minnesota License No. 19552

Statement of Evidence:**L093**

East Quarter Corner of Section 9, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post at the corner location and bearing trees were recorded.
6" Blk Oak N 6 1/2 W 772 links
- 2002 No resurvey information was found on this corner in the Benton County records.
- 2004 BWK established corner at intersection of fence lines north-south and east-west as an obliterated corner. This position is 1.5 feet south and 9.9 feet west of the lost position.
County Coordinates by BWK to set corner:
NAD 83 (1996 Adjustment)
N- 124212.311
E- 494748.429
- 2008 Westwood Professional Services, Inc. found a 1/2" iron pipe capped 10918 at fence lines south, east, and west. Established reference ties. BWK coordinates were verified.