

Certified, Filed and or Recorded on
Mar. 08, 2011 AT 12:36PM


Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 15, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 08/24/09 found a 1/2" IRON PIPE
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittetoch
Benton County Surveyor
License No. 19552

Date: 07 March 2011

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:

L153

East Quarter Corner of Section 15, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.
 10" Bur Oak S 2 E 944 links
- 1971 William Lunser, LS No. 9394, set a ½" iron pipe for the corner by lost method measuring 2679.04 feet to the NE and SE corners of Section 15 and filed a Certificate of Location (Doc. No. 133426). (This is also noted in County Surveyor's Record Book 1, page 189).
- 1995 Lunser information gives distances of 2679.84 feet to the NE and SE corners.
- 2004 Danny Kron, LS 42621, found iron pipe. He measured 2679.19 feet to NE corner and 2680.66 feet to the SE corner.
 County Coordinates obtained by traverse by Surveying & Engineering Professionals, Inc.
 NAD 83 (1996 Adjustment)
 N- 118653.667
 E- 500107.135
- 2004 MN/DOT found iron pipe.
 County Coordinates obtained GPS
 NAD 83 (1996 Adjustment)
 N- 118654.089
 E- 500107.061
- 2009 MnDot found a ½" iron pipe and established reference ties. (Certificate of Location Doc. No. 368989)
- 2009 Westwood Professional Services, Inc. found a ½" iron pipe 2678.88 feet from the NE corner and 2680.97 from the SE corner. Coordinate position is in agreement with 2004 locations by Danny Kron, LS 42621 and MN/DOT. Established reference ties.

 County Coordinates obtained GPS
 NAD 83 (1996 Adjustment)
 N- 118653.98
 E- 500107.22

A 368989

Certified, Filed and or Recorded on
Sep. 22, 2009 AT 12:21PM


Signed: BW
MARILYN J NOVAK B V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER
Fee Amount: \$46.00

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 15, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09-10-09 found a 1/2 Inch Iron pipe
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed a _____
DATE



Not to scale
All distances are chained level

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Kevin J. Metz Date 9-14-2009 License No. 40343
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer
MNDOT

Statement of Evidence:**East Quarter Corner of Section 15, Township 36 North, Range 30 West, Minden Township,
4th Principal Meridian, Benton County, Minnesota.**

- 1852 Original US General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.
10" Bur Oak S 2 E 944 links
- 1971 William Lunser, LS No. 9394, set a ½" iron pipe for the corner by lost method measuring 2679.04 feet to the Northeast and Southeast Corners of Section 15 and filed a Certificate of Location, Document No. 133426. (This is also noted in County Surveyor's Record Book 1, page 189).
- 1995 William Lunser's information gives distances of 2679.84 feet to the Northeast and Southeast Corners of Section 15.
- 2004 Dan Kron, RLS 42621, found an iron pipe. He measured 2679.19 feet to Northeast Corner of Section 15 and 2680.66 feet to the Southeast Corner of Section 15. Surveying & Engineering Professionals, Inc. provided the coordinates for the section corner.
County Coordinates obtained by traverse (for reference only)
NAD 83 (1996 Adjustment)
N- 118653.667
E- 500107.135
- 2003 On December 1st, 2003, The Minnesota Department of Transportation found a ½" iron pipe as described above. Reference ties were established.
County Coordinates obtained by GPS (for reference only)
NAD 83 (1996 Adjustment)
N- 118654.09
E- 500107.06
- 2009 On September 10th, 2009, The Minnesota Department of Transportation found a ½" iron pipe. Reference Ties were verified as shown on the front of this document. The Minnesota Department of Transportation accepts the ½" iron pipe as the correct location of the East Quarter Corner of Section 15.


For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.

Minden

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 1 day of March, 1971
I did restore the east quarter corner of Section 15,
Twp. 36, Rg. 36, Benton County, Minnesota, which
was evidenced by single proportion measure

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of a 1/2" Iron Pipe and that
I did establish witness or reference monuments as shown below:



133426

I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

William H. Johnson

Minn. Registration No. 9394.

Office of the Register of Deeds,
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 9th day of February, 1973.

J. A. Johnson
Register of Deeds

By *Marilyn Novak* Deputy.