

4-13

A 373401

Certified, Filed and or Recorded on
Apr. 13, 2010 AT 01:20PM

Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER
Fee Amount: \$46.00

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 24, Township 36 North, Range 30 West
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:


On 4/08/2010 found a 1/2" Iron pipe, down 1.0'
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed a _____
DATE

NOT TO SCALE

Section 13



Azimuths based on N.A.D. 83
1996 Adjust (H.A.R.N.)

Section 24

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Kevin J Metz Date 4-13-2010 License No. 40343
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

All MNDOT - Benton

Statement of Evidence: North Quarter Corner of Section 24, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this Corner set a wood post at this location and bearing trees were recorded.
7" Blk Oak S 4 1/2 E 180 links

1999 William Lunser, LS 9394, set a 1/2" pipe at the lost location. He filed a Certificate of Location (#283119) and notes a distance of 2665.09 feet to the NE Corners Sec 23 and Sec 24.

2002 We found no other record information on this Corner in the Benton County records.

2003-2005 On 12/1/2003 The Minnesota Department of Transportation, in cooperation with Gary Stevenson, Benton County Surveyor, found a 1/2" iron pipe as described in 1999. The location agreed with information from 1999. No reference ties were near.

County Coordinates obtained by GPS (for reference only)
NAD 83 (1996 Adjustment) N- 115994.00, E- 508095.25

2010 On 1/20/2010 The Minnesota Department of Transportation again found a 1/2 inch pipe.
On 4/08/2010, The Minnesota Department of Transportation dug out the 1/2 inch pipe, and set two sign posts as accessories, as shown on the front of this document. The Minnesota Department of Transportation accepts the 1/2 inch pipe as the correct location for the North Quarter Corner of Section 24, Township 36 North, Range 30 West, 4th Principal Meridian, Benton County, Minnesota.

For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.

A 372084

Certified, Filed and or Recorded on
Feb. 05, 2010 AT 02:05PM


Signed: CK
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER
Fee Amount: \$46.00

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 24, Township 36 North, Range 30 West
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 1/20/2010 found a 1/2" Iron pipe
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed a _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature *Kevin J Metz* Date 2-4-2010 License No. 40343
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence: North Quarter Corner of Section 24, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this Corner set a wood post at this location and bearing trees were recorded.

7" Blk Oak S 4 1/2 E 180 links

1999 William Lunser, LS 9394, set a 1/2" pipe at the lost location. He filed a Certificate of Location (#283119) and notes a distance of 2665.09 feet to the NE Corners Sec 23 and Sec 24.

2002 We found no other record information on this Corner in the Benton County records.

2004-2005 On 12/1/2003 The Minnesota Department of Transportation, in cooperation with Gary Stevenson, Benton County Surveyor, found a 1/2" iron pipe as described in 1999. The location agreed with information from 1999. No reference ties were near.

County Coordinates obtained by GPS (for reference only)
NAD 83 (1996 Adjustment) N- 115994.00, E- 508095.25

2010 On 1/20/2010 The Minnesota Department of Transportation again found a 1/2 inch pipe. The Minnesota Department of Transportation accepts the 1/2 inch pipe as correct location for the North Corner of Section 24, Township 36 North, Range 30 West, 4th Principal Meridian, Benton County, Minnesota.


For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER corner of Section 24, Township 36, Range 30, 4th P.M.
Benton County, Minnesota.

On Dec 17, 1999, a one half inch iron pipe (I.P.) was placed at this location.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunser 1-24-02

William F. Lunser, L.S. Date
Mn Reg No 9394

OFFICE OF THE COUNTY RECORDER
Benton County, Minnesota

I hereby certify that this document was filed in this office at ___:___ M. on the ___ day of _____, 20__.

County Recorder _____

By _____ Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE:

No records were found to indicate use or remonumentation of this corner after its original placement by the U.S. Government Survey.

With no well defined fence or occupation lines to act as accessories, this corner is presumed to be lost.



William F. Lunser, L.S.

283119

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

FEB 21 4 16 PM '02

MARILYN J. NOVAK
COUNTY RECORDER

BY Marilyn J. Novak DEPUTY