

Certified, Filed and or Recorded on
Sep. 22, 2009 AT 12:21PM


Signed: BW
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER
Fee Amount: \$46.00

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 14, Township 36, Range 30
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 09-09-09 found a 1/2" inch iron pipe. (RLS cap was destroyed)
DATE
- left monument as found lowered monument removed monument (explain)
- On _____ placed a _____
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Kevin J. Metz Date 9-10-2009 License No. 40343
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer
MNDOT

Statement of Evidence:**Northeast Corner of Section 14, Township 36 North, Range 30 West, Minden Township, 4th Principal Meridian, Benton County, Minnesota.**

1852 Original US General Land Office survey established this corner and a wood post was set for the corner and bearing trees were recorded.

16" Bur Oak	S 15 E	565 links
20" Bur Oak	S 89 3/4 W	600 links

1961 M. W. Carley ties:

Corner FP	N	22.19
TP	NE	37.85
PP	NW	63.15

1995 Kevin Festler, LS 22702, set a ½" iron pipe, LS 16097, at the intersection of fence line north and roads west, south, and east as an obliterated corner and filed a Certificate of Location, Document No. 230320.

Comstock and Davis performed GPS work under contract with Benton County established coordinates on the ½" iron pipe.

Coordinates obtained by GPS (for reference only)

NAD 83 (1986 Adjustment)

N- 121204.626

E- 505393.773

1999 William Lunser used corner to set East Quarter Corner of Section 14.

Note: 1961 and 1995 positions do not appear to agree with each other.

2003 On October 14th, 2003, The Minnesota Department of Transportation found a ½" iron pipe with L.S. cap destroyed. In conjunction with the Benton County Surveyor, Gary Stevenson L.S. 12684, it was determined to accept the iron pipe set by Mr. Festler, L.S. 22702, in 1995. Reference ties were established.

County Coordinates obtained by GPS (for reference only)

NAD 83 (1996 Adjustment)

N- 121204.944

E- 505393.309

2009 On September 9th, 2009, The Minnesota Department of Transportation found a ½" iron pipe with the cap destroyed. Reference ties were verified as shown on the front of this document. The Minnesota Department of Transportation accepts the ½" iron pipe as the correct location of the Northeast Corner of Section 14.

For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 14, Township 36, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On 2-2-95 found a nothing
DATE

left monument as found, lowered monument, removed monument (explain)

On 2-13-95 placed a 1/2 inch iron pipe monument capped RLS 16097
DATE

SKETCH OF REFERENCE TIES



NOT TO SCALE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Kenneth P. [Signature] 8/17/1995
SIGNATURE DATE

Registration No. 22702
 Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorders office at _____ M. on the _____ day of _____ A.D., 19 _____

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

The northeast corner of Section 14, Township 36, Range 30, 4th Principal Meridian, Benton County, Minnesota, was set under the Public Land Survey as a post with bearing trees. No trace of post or trees now exists.

A search by Benton Co. Highway personnel of available county survey records revealed no additional information on this corner.

In 1995, Comstock & Davis, Inc., while re-monumenting section corners for the purpose of G.P.S. work for Benton County found evidence of the northeast corner of Section 14, TWP. 36, RNG 30 by the north-south and east intersection of County Road No. 50 and an old road bed. The northeast corner position was further evidenced by a fence line to the north. Comstock & Davis, Inc. compared the location of this intersection to the original U.S. Government Survey and found the position to be within reason of the Public Land Survey records. Comstock & Davis, Inc. placed a 1/2 inch iron pipe monument capped RLS No. 16097 at said intersection. Comstock & Davis, Inc. accepted the position of the 1/2 inch iron pipe as the position for the northeast corner of Section 14. Refer to Job No. 945017.

2 3 0 3 2 0

STATE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MINN
CERTIFIED TO BE FILED
AUG 31 1995

AUG 31 12 53 PM '95

ALICE J. HARRIS
CO.

BY *Mm* *AM*