

Benton County Surveyor's Office
 Jerome C. Wittstock, County Surveyor
 Minnesota License No. 19552

Statement of Evidence:

L332

Northeast Corner of Section 33, Township 36 North, Range 30 West, Minden Township,
 4th Principal Meridian, Benton County, Minnesota.

1852 Original US General Land Office survey established this corner and set a wood post at this location and bearing trees were recorded.

6" Burr Oak	N 65 1/2 E	677 links
6" Blk. Oak	N 21 1/2 W	471 links

Pre 1940 MN/DOT notes by C. H. West for TH 95 show corner assumed at intersection of fences east, west, and south.

1980 William Lunser, LS 9394, set a 1/2" iron monument at the intersection of very old fences from the east and south. This was verified by measurements to the section corners 1 mile north and 1 mile east. He established reference ties. A Certificate of Location (#158856) was recorded.

1992 County Coordinates from MN/DOT:
 NAD 83 (1986 Adjustment)
 N-105443.288
 E-495003.736

1995 Comstock and Davis performed GPS work under contract with Benton County and Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a 1/2 " iron pipe:
 N- 105443.835
 E- 495003.870

2001 On October 31, 2001 Westwood Professional Services, Inc. found a 1/2" iron monument at the intersection of fence lines (mostly down) from the south and from the east. We found blazes in the trees that may be from Mr. Lunser's tree ties. We removed the 1/2" iron monument and set a cast iron monument at the location and established new ties.

2003 County Coordinates Obtained by Sidetie
 NAD 83 (1996 Adjustment)
 N- 105443.970
 E- 495003.300

2008 Westwood Professional Services, Inc. found a CIM, established new reference ties and verified the 2003 coordinates.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North east Corner of Section 33, Township 36, Range 30, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On 10-10-80 found a old fence corner
DATE

left monument as found, lowered monument, removed monument (explain)

On 10-10-80 placed a 1/2 inch iron pipe
DATE

SKETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunce 10-10-80
SIGNATURE DATE

Registration No. 9394

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

County Recorder
OFFICE OF THE REGISTER OF DEEDS
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 3 P.M. on the 7th day of April A.D., 1981

County Recorder
Register of Deeds F.A. Johnson


By _____, Deputy

DOCUMENT NO. 152856

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 10th day of October, 1980
 I did locate the northeast corner of Section 33,
 Twp. 36, Rg. 30, Benton County, Minnesota, which
 was evidenced by a very old fence corner, fence runs east and
 south, which was verified by measurements to section corners
1 mile north and 1 mile east. 1/4 corner 1/2 mile north is
very near mid point on line between section corners.

I further certify that in order to perpetuate said corner I did
 at the exact location thereof place a permanent marker consisting
 of 1/2 inch iron pipe and that
 I did establish witness or reference monuments as shown below:



158856

I hereby certify that the
 above is true and correct
 and that I am a registered
 Land Surveyor under the laws
 of the State of Minnesota.

Walter A. Larson

Minn. Registration No. 9394

Office of the County Recorder,
Benton County, Minn.

I hereby certify that the within
 instrument was filed for record
 in this office on the 7th day of
April, 1981. 3 P.M.

F. A. Johnson
 County Recorder

By _____ Deputy.