

283100

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

FEB 21 2 55 PM '02

MARILYN J. NOWAK
COUNTY RECORDER
BY Marilyn Nowak DEPUTY

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 2, Township 36, Range 31


4th Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

On 9-29-2000 found a 0.50 INCH IRON PIPE
DATE

left monument as found lowered monument removed monument (explain)

On 9-29-2000 placed a MINNESOTA HIGHWAY DEPARTMENT CAST IRON MONUMENT
DATE OVER PIPE



⊙ = MINNESOTA HIGHWAY DEPARTMENT
CAST IRON MONUMENT

ALL DISTANCES ARE CHAINED LEVEL

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature [Signature] MNDOT Date 10-31-2001 License No. 40343

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence: North Quarter Corner Section 2, Township 36 North, Range 31 West, 4th Principal Meridian, Benton County, Minnesota.

The original Public Land Survey was run in 1849 and 1850 by Mr. Theodore Conkey and Mr. John Ryan, and a wood post was used to mark the corner. Bearing Tree ties were established to a Black Oak and a Burr Oak.

On July 5th, 1977, Mr. William Lunser, Registered Land Surveyor, placed a 0.5 inch iron pipe by methods described in Document Number 147065, Benton County Recorder's Office.

On September 29, 2000, The Minnesota Department of Transportation searched the area and found a 0.5 inch iron pipe, and three of Lunser's 1977 bearing ties. A Cast Iron Monument was placed over the 0.5 inch iron pipe. The Minnesota Department of Transportation accepts this position as the correct location for the corner.

For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Set the

March Quarter Corner of Section 2, Township 36, Range 31, 4th P.M.

STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On 7-5-77 found a Occupation of fences North and West and field
DATE line South

left monument as found, lowered monument, removed monument (explain)

On _____ placed a 1/2 inch iron pipe
DATE

SKETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lusser 7-5-77
SIGNATURE DATE

Registration No. 9394

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the 20th day of December A.D., 1977


Register of Deeds F.A. Johnson
By _____, Deputy

DOCUMENT NO. 147065

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 5th day of July, 19 77
I did Set the North Quarter corner of Section 2,
Twp. 36, Rg. 31, Benton County, Minnesota, which
was evidenced by Occupation of fences North and West
and field line South

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of 1/2 inch iron pipe and that
I did establish witness or reference monuments as shown below:



147065

I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

Walter P. Jensen

Minn. Registration No. 9394

Office of the Register of Deeds,
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 30 day of December, 1977 at 9 A.M.

F.A. Johnson
Register of Deeds

By _____ Deputy.