

279107

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON

Oct 22 2 45 PM '01


MARILYN J. NOVAK  
COUNTY RECORDER  
BY Marilyn J. Novak *REPUTY*

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 3, Township 36 N, Range 29 W  
4th Principal Meridian, State of Minnesota, County of BENTON

At the corner location shown on the sketch:

- On 4/18/2001 found a TOP 8" OF A BROKEN CAST IRON MONUMENT, FLUSH  
DATE
- left monument as found     lowered monument     removed monument (explain)
- On 4/19/2001 placed a NEW BENTON COUNTY CAST IRON MONUMENT, DOWN 1'  
DATE  
INPLACE OF FOUND BROKEN CIM.



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature Samuel J. Debo Date 6-4-2001 License No. 40341

Title:  Land Surveyor     Professional Engineer     County Surveyor     County Engineer

Statement of Evidence

Northeast Corner of Section 3, Twp. 36 N, Rng. 29 W  
4<sup>th</sup> P.M., Benton County, Minnesota

Copies of notes from the original GLO survey, located in the office of the Benton County Highway Department, state that a wood post was set to mark the corner. Physical remains to evidence of this corner could not be found.

April 1929; H. G. Elletson, County Surveyor, noted an iron pipe marking the corner that measured 2635.2' East of the North Quarter Corner of Section 3 and 1261.3' North of the Northeast Corner of the Northeast Quarter of the Northeast Quarter of said Section 3.

December 1997; Sidney P. Williamson (RLS # 10918) placed a Benton County Cast Iron Monument as shown on the Certificate of Location of Government Corner on file in the Benton County Highway Department. Mr. Williamson's based his location on the survey of Section 3 by H. G. Elletson in 1929. His location is based on measurements to the east and the location of an existent fence line.

April 2001; Sam DeLeo, RLS #40341, found a broken standard Benton County cast iron monument flush with the gravel surface. Also found was an iron rod at the Northeast Corner of the Northeast Corner of said Section 3. H. G. Elletson's 1929 survey refers that an iron monument was set at this location 1261.3' South of the Northeast Corner of said Section 3. The distance measured from the found iron monument to the found broken CIM was 1262.13'. The distances compare well. The location of Williamson's CIM was held. A new Benton County cast iron monument was set in its place 1' below the gravel surface. New reference ties were recorded and a new Certificate of Location of Government Corner was made.

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 3, Township 36, Range 29, 4<sup>TH</sup> P.M.

STATE OF MINNESOTA, County of BENTON


At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On 12.08.97 placed a BENTON COUNTY CAST IRON MONUMENT  
DATE

### SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Sidney P. Williamson 12/9/97  
SIGNATURE DATE

Registration No. 10918

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

### OFFICE OF THE COUNTY RECORDER

County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_

County Recorder \_\_\_\_\_

By \_\_\_\_\_, Deputy

DOCUMENT NO. \_\_\_\_\_

Statement of Evidence:

**NORTHEAST CORNER OF SECTION 3, TOWNSHIP 36 NORTH, RANGE 29 WEST**

1. A post was set by U.S. Government Survey in 1855. No evidence of the post or bearing trees remain.
2. In reviewing Benton County Survey Records, a survey of Section 3, by H.G. Elletson, was performed in April of 1929. He denotes an iron monument and post at the northwest corner and measures east 2,703.2 feet to an iron monument at the north quarter corner, then again east to an iron monument at the northeast corner 2,635.2 feet.
3. In December 1997, a survey crew under my direct supervision, measured the north line of Section 3. A Benton County Cast Iron Monument was found at the northwest corner. Measuring east 2,709.80 feet, a Benton County Cast Iron Monument was found at the north quarter corner. Measuring east 2,637.43 feet, a Benton County Cast Iron Monument was set at the northerly extension of an old barbed wire fence and the center line of the Township Road. This fence was referred to in the 1929 survey by H.G. Elletson.

2 4 6 0 8 5

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON

DEC 15 10 27 AM '97

ALICE G. ENGLISH-JER  
COUNTY RECORDER

BY mm DEPUTY mm