

Statement of Evidence:

K132

Northeast Corner of Section 13, Township 36 North, Range 29 West, St. George Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Corner established by GLO and marked by a wood post with bearing trees noted as.

| | | |
|--------------|--------|----------|
| 12" Blk Ash | N 60 W | 40 links |
| 12" Elm | N 39 E | 72 links |
| 10" Elm | S 37 W | 28 links |
| 10" Basswood | S 44 E | 18 links |

Line trees were noted as a 18" Blk Oak South 24.59 chains and a 16" Blk Ash North 15.28 chains.

1933 County Engineer's notebook No. 67 shows road survey by H. G. Elletson starting at this corner and running west. Corner is shown as a spike in center of road with fence north with ties:

| | | |
|------------|----|-------|
| 36" Willow | NE | 55.4' |
| 30" Willow | SE | 46.3' |

2005 WSN searched corner area and did not any corner marker and no evidence remains of the 1933 ties. Set a PK nail for a temporary corner in the center of east-west road and in line with old fence line north. Distance to the North $\frac{1}{4}$ corner of Section 13 checks reasonably with the 1933 highway survey.

County Coordinates obtained by GPS to PK nail:

NAD 83 (1996 Adjustment)

N- 122039.158

E- 542664.334

Accepted PK Nail position as the best evidence of the obliterated corner position and replaced the PK Nail with a $\frac{1}{2}$ " iron pipe.