

Certified, Filed and or Recorded on
Nov. 05, 2008 AT 08:29AM


Signed: M
MARILYN J NOVAK G V I
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 9, Township 37, Range 31
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 9-24-08 found a CAST IRON MON.
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



9.10



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Handwritten Signature]
Deputy County Surveyor
License No. 43932

Date: 11/3/08

Statement of Evidence:

F093

East Quarter Corner of Section 9, Township 37 North, Range 31 West, Watab Township,
4th Principal Meridian, Benton County, Minnesota.

- 1850 Original US General Land Office survey set a wood post in a mound with a pit for the corner location.
- 1972 Certificate of Survey, filed as Doc. No. 132159, M. W. Carley, LS 855, set corner lost with 2660.51 feet to section corners.
- 1981 Reference ties to 1 ½ " x 30" iron pipe, 4" below surface, 2 feet east of center of north-south road:
- | | | |
|--------------|------|-------|
| 4" Twin Pine | West | 90.70 |
| 6" Pine | WSW | 43.79 |
| 5" Pine | SW | 83.45 |
- 1982 David Regan, LS 12236, found a 1 ½ " pipe, 2 feet east of the centerline of a north/south township road and on a fence line west. He replaced the iron with a cast iron monument and filed a Certificate of Location (#162597). Same ties as 1981.
- 1987 This corner is noted on the following:
SURVEYORS CERTIFICATE FOR EDWARD WEILSON dated 12/18/1987 by William Lunser, LS 9394.
- 2004 MN/DOT
County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N-156097.729
E-462823.470
- 2008 Westwood Professional Services, Inc. found a CIM 2 feet east of the centerline of 15th Ave NW. No ties from Certificate of Location #162597 were found at the time of survey. CIM measures 2660.96 feet to the NE corner and 2660.17 feet to the SE corner of Section 9 and fits a fence line to the west. CIM is accepted as marking the obliterated position for this location. Coordinates obtained by GPS coincide with 2004 MN/DOT position.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter _____ Corner of Section 9, Township 37, Range 31, 4th P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 6/17/82 found a 1½ inch iron pipe 2 feet east of center line
of township road north-south and on fence line west
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 6/17/82 placed a Benton County cast iron monument
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David J. Ryan 7/13/82
SIGNATURE DATE

Registration No. 12236

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS ~~COUNTY REGISTER~~
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 10 AM on the 27 day of July A.D., 1982

Register of Deeds F.A. Johnson

By _____, Deputy

DOCUMENT NO. 162597