

Certified, Filed and or Recorded on  
Dec. 24, 2008 AT 08:52AM

Signed: BW  
MARILYN J NOVAK B V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTH EAST Corner of Section 36, Township 37, Range 31  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On 10-9-08 found a CAST IRON MONUMENT

left monument as found       lowered monument       removed monument (explain)

On \_\_\_\_\_ placed an \_\_\_\_\_



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Chris Hyslop  
Deputy County Surveyor  
License No. 43932

Date: 12/17/08

Benton County Surveyor's Office  
Chris Hogle, Deputy County Surveyor  
Minnesota License No. 43932

**Statement of Evidence:**

F362

Northeast Corner of Section 36, Township 37 North, Range 31 West, Watab Township,  
4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

26" Burr Oak	N 56 E	155 links
8" Burr Oak	N 40 W	62 links
6" Blk. Oak	S 78 E	316 links

1923 County Engineer's Notebook No. 32 contains a survey for SR No. 1 running south to north and terminating at this corner. Same ties as in 1926.

1926 County Engineer's notebook 51 and road alignment information (also shown in the County Surveyor's Record Book 1, page 381) note the following reference ties and a distance of 2773.5 feet to the North 1/4 corner Sec 31-37-30.

Corner F.P.	W	29.0
6" R. Oak	SE	59.2

1938 County Engineers' Notebook No. 116 shows survey of SAR 1 running from south to north. Notes show corner being a spike in center of north-south road, SAR No. 4 east, and fence west. Ties:

14" Oak W	36.15'
10" Oak SE	58.2'

Stationing gives distances of 2653.1 feet to the SE corner and 2930.0 feet to the NE corner with a delta angle of 0-25' left.

1961-1968 notes show the corner having the following reference ties.

T.P.	SW	74.45
Twin 10" Oak	W	91.6
P.P.	NE	47.4

Undated notes show a 2" iron pipe down 1 foot with the following reference ties.

Twin 8" R. Oak	SW	89.88
20" R. Oak	SE	141.35
P.P.	NE	47.2

1990 Paul Wellen, LS 10461, found a 3/4" iron pipe at the intersection of the centerline of County Road 1 (running north and south) and the centerline of County Road 4 (from the east) and a tree line (from the west). He set a cast iron monument at the position and established reference ties.

2002 Westwood Professional Services, Inc. found a cast iron monument at the intersection of the centerlines of County Road 1 (running north and south) and County Road 4 (from the east) and a tree line (from the west). Checked for old ties with most destroyed, but Oaks to the SW are still there. Possible remains of original oak BT to the SE needs further review.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-137462.143  
E-478581.660

2008 Westwood Professional Services, Inc. found a cast iron monument at the corner location. Further investigation of our 2002 information, we found no conclusive evidence that any remnants of original BT's remain. We did find a twin 14" red oak West 91.6 feet, consistent with 1961-1968 ties. CIM is accepted as marking the obliterated position for this corner. Coordinates obtained by GPS coincide with 2002 position.

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 36, Township 37, Range 31, 4 P.M.

STATE OF MINNESOTA, County of BENTON


The corner location shown on the sketch:

On 7 AUG 90 found a 3/4" IRON PIPE  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On 7 AUG 90 placed a COUNTY MONUMENT  
DATE

### SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Paul J. Miller 1/14/91  
SIGNATURE DATE

Registration No. 10461

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

### OFFICE OF THE COUNTY RECORDER

County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_

County Recorder \_\_\_\_\_

By \_\_\_\_\_, Deputy

DOCUMENT NO. \_\_\_\_\_

Statement of Evidence:

Northeast corner, of Section 36, T  
37 N, R 31 W, of the 4th Principal Meridian.

1. During the G.L.O. Survey of 1852, Mr. Theodore Conkey, a U.S. Deputy Surveyor, set a wood post to mark this corner.
2. A search of the Benton County Surveyor records indicated a corner with two (2) reference ties for the location of this corner.
3. On August 7, 1990, Paul E. Wellen & Associates, Inc., found a 3/4 inch iron pipe in the intersection of the center line of Benton County Road 1 (north-south) and the center line of Benton County Road 4 (east) opposite a tree line to the west and placed a cast iron monument at this location. We also established new reference ties as indicated.

OFFICE OF  
BENTON COUNTY RECORDER  
- BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AND/OR RECORDED ON  
APR 29 1 47 PM '91  
ALICE C. ENGELMEYER  
COUNTY RECORDER  
BY AL DEPUTY

202364