

Certified, Filed and or Recorded on
Oct. 31, 2008 AT 08:34AM


Signed: Ju
MARILYN J NOVAK G U
BENTON COUNTY MINNESOTA
MARILYN J NOVAK
COUNTY RECORDER

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 2, Township 38, Range 32
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 8-18-08 found a CAST IRON MON
- left monument as found lowered monument removed monument (explain)
- On _____ placed an _____



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature [Signature]
Deputy County Surveyor
License No. 43932

Date: 10/14/08

Benton County Surveyor's Office
 Chris Høglund, Deputy County Surveyor
 Minnesota License No. 43932

Statement of Evidence:

E023

The East Quarter Corner of Section 2, Township 38 North, Range 32 West, West Langola Township, 4th Principal Meridian, Benton County, Minnesota.

- 1852 Original US General Land Office surveyor, Edwin James, Jr., set a wood post at this location and bearing trees were recorded.
- | | | |
|-------------|--------|-----------|
| 8" Bur Oak | N 55 E | 175 links |
| 12" Bur Oak | S 11 W | 367 links |
- 1977 On June 23, 1977 William Lunser, LS 9394, set a 1/2" iron pipe at the intersection of the centerline of a road along the NE1/4 and a fence line along the 1/4 section line of Sections 1 & 2. He filed a Certificate of Location (#147082). The iron is 3.3 feet south of an east/west fence line.
 This corner is 2644.15 feet south of the NE Corner of Sec 2.
 This corner is 2673.50 feet north of the SE Corner of Sec 2.
- 1978 On February 28, 1978 Paul Wellen, LS 10461, found a 3/4" iron pipe at the corner location, which was 3' south of a fence line running east and west. He filed a Certificate of Location (#151878).
- 1979 On July 10, 1979 Paul Wellen noted that a distance shown on Document No. 147082 was incorrect. The distance reads 2644.15 feet and it should instead read 2653.50 feet.
- 1989 On November 20, 1989 William Lunser set a cast iron monument using existing ties and filed a Certificate of Location (#195967). He shows a distance of 2653.50 feet to the NE corner of Section 2.
- 2002 On January 24, 2002 Westwood Professional Services, Inc. found a Highway Department Cast Iron Monument at the corner location.
 County Coordinates by GPS
 NAD 83 (1996 Adjustment)
 N- 193517.349
 E- 440600.870
- 2008 Westwood Professional Services, Inc. found a CIM at this location. Measures 2653.62 feet the NE corner of Section 2 and 2668.32 feet to the SE corner of section 2. CIM is accepted as marking the obliterated corner position.
 Observation by GPS confirms 2002 coordinates.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 2, Township 38, Range 32, 4th P.M.

STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 11-20-89 placed a Benton County Cast Iron Mon.
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] SIGNATURE 1/5/90 DATE

Registration No. 9394

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

- 6-23-77 Lunser Survey Co. placed a $\frac{1}{2}$ " iron pipe at the $\frac{1}{4}$ corner location. It was placed on the projection of a centerline of a road along the east line of the NE $\frac{1}{4}$ to the intersection of a fence line along the $\frac{1}{4}$ section line. A certificate of location was filed with the county recorder.
- 7-10-79 Paul Wellen, Land Surveyor, noted after using the NE and East $\frac{1}{4}$ corners of this section that the distance shown on the certificate of location, from the E $\frac{1}{4}$ corner to the NE corner was incorrect. The distance stated was 2644.15 and should be corrected to read 2653.50.
- 11-20-89 Found the same $\frac{1}{2}$ " iron pipe, verified it's location with existing ties and placed a cast iron mon.

1 9 5 9 6 7

OFFICE OF
BENTON COUNTY RECORDER
BENTON COUNTY, MN
CERTIFIED TO BE FILED
AND/OR RECORDED ON

JAN 11 8 36 AM '90

ALICE G. ENOCHMEYER
COUNTY RECORDER

BY *[Signature]* DEPUTY

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East 1/4 Corner of Section 2, Township 38, Range 32, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Filed under West 1/4 Corner Section 1, T 38 R 32

Certificate # 151878

March 1979

*Also See Next Page
CERTIFICATE # 147082*

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE DATE

Registration No. _____

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 _____

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

Should BE EAST 1/4 corner Section 2, T38 R32 Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East 1/4 Corner of Section 1, Township 38, Range 32, 4 P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

- On 2-28-1978 found a 3/4" iron pipe, 3.4' off the fence-line east-west
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Paul E. Skellen
SIGNATURE DATE

Registration No. 10461

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

County Recorder
OFFICE OF THE REGISTER OF DEEDS
County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 10 9 .M. on the 26th day of March A.D., 19 77

Register of Deeds F. G. Johnson
By _____, Deputy


DOCUMENT NO. 151878

Should BE EAST 1/4 CORNER SECTION 2, T38 R32

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 28 day of February, 19 78
I did find the West 1/4 corner of Section 1,
Twp. 38, Rg. 32, Benton County, Minnesota, which
was evidenced by 3/4" iron pipe, 3.4' off the fence-line, (east-west)

I further certify that in order to perpetuate said corner I did
at the exact location thereof place a permanent marker consisting
of _____ and that
I did establish witness or reference monuments as shown below:



151878

I hereby certify that the above
is true and correct and that I am
a registered Land Surveyor under
the laws of the State of Minnesota.

Sandy Nelson

Minn. Registration No. 10461

Office of the County Recorder,
Benton County, Minn.

I hereby certify that the within instrument
was filed for record in this office on the
26th day of March, 19 79
at 10 a.m.

F.A. Johnson
County Recorder

By _____ Deputy.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 2, Township 38, Range 32, _____ P.M.

STATE OF MINNESOTA, County of Benton

At the corner location shown on the sketch:

On 6-23-1927 found a monument evidenced by projection of centerline of road along east line ^{DATE} to intersection of fence line along 1/4 sec. line in Section 1 & 2

left monument as found, lowered monument, removed monument (explain)

On _____ placed a 1/2 inch iron pipe
DATE

SKETCH OF REFERENCE TIES



Refer to next page

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

William F. Lunsar 6-23-1927
SIGNATURE DATE

Registration No. 9394

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Benton

I hereby certify that this document was filed in the Reg. of Deeds office at 9 A.M. on the 20th day of December A.D., 1927


Register of Deeds T. G. Johnson
County Recorder By _____, Deputy

DOCUMENT NO. 147082

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that on the 23 day of June, 1977
 I did Set the East Quarter corner of Section 2,
 Twp. 38, Rg. 32, Benton County, Minnesota, which
 was evidenced by Projection of centerline of road along
east line NE 1/4 to intersection of fence line along 1/4
sec. line in Sections 1 and 2

I further certify that in order to perpetuate said corner I did
 at the exact location thereof place a permanent marker consisting
 of 1/2 inch iron pipe and that
 I did establish witness or reference monuments as shown below:



I hereby certify that the above is true and correct and that I am a registered Land Surveyor under the laws of the State of Minnesota.

William J. Johnson

Minn. Registration No. 9394

147082 County Recorder
 Office of the Register of Deeds,
Benton County, Minn.

I hereby certify that the within instrument was filed for record in this office on the 20 day of December, 1977 at 9 A.M.

F.A. Johnson
 Register of Deeds County Recorder

By _____ Deputy.