

Certified, Filed and or Recorded on  
May 06, 2008 AT 01:19PM


Signed: MJ  
MARILYN J NOVAK G V ✓  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH EAST Corner of Section 2, Township 36, Range 30  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

- On 1-23-07 found a 1 1/2" Iron pipe  
DATE
- left monument as found     lowered monument     removed monument (explain)
- On \_\_\_\_\_ placed an \_\_\_\_\_  
DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock Date 06 May 2008 License No. 19552  
Title:  Land Surveyor     Professional Engineer     County Surveyor     County Engineer

Benton County Surveyor's Office  
 Jerome C. Wittstock, County Surveyor  
 Minnesota License No. 19552

**Statement of Evidence:**

L022

The Northeast Corner of Section 2, Township 36 North, Range 30 West, Minden Township, 4<sup>th</sup> Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey established this corner and note a wood post was set with bearing trees marked.

12" Elm	N 84 E	30 links
18" Elm	N 35 W	28 links
8" Elm	S 48 W	119 links
16" Elm	S 72 E	25 links

1939 County Engineer's Notebook No. 127 contains survey of CAR 29 running west to east on section line. Corner is shown as an iron pipe in center of road in line with fences north and south. Ties:

FP	NW	39.55
FP	NE	38.15

1961-1968 The following reference ties are noted in County Highway records.

PP	S	28.73
24" Elm	S	99.13
Cor FP	N	31.38

1995 Kevin Festler, LS 22702, found a 1 1/2" pipe at the intersection of the centerline of County Road 44 and a fence line north. A Certificate of Location (#230315) was filed.

Comstock and Davis performed GPS work under contract with Benton County. County Coordinates Obtained by GPS NAD 83 (1986 Adjustment) to a 1 1/2" iron pipe:

N- 132195.406  
 E- 505214.046

2008 Westwood Professional Services, Inc. found a 1 1/2" iron pipe fitting centerline of County Rd. 44 (east/west road). Established reference ties.

County Coordinates Obtained by GPS  
 NAD 83 (1986 Adjustment)

N- 132195.508  
 E- 505213.549

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Northeast Corner of Section 2, Township 36, Range 30, 4th P.M.

STATE OF MINNESOTA, County of Benton


At the corner location shown on the sketch:

On 2-16-95 found a 1 1/2 inch iron pipe  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



*Not To Scale*

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 8/17/1995  
SIGNATURE DATE

Registration No. 22702  
 Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of \_\_\_\_\_

I hereby certify that this document was filed in the Co. Recorders office at \_\_\_\_\_ .M. on the \_\_\_\_\_ day of \_\_\_\_\_ A.D., 19 \_\_\_\_\_

County Recorder \_\_\_\_\_  
By \_\_\_\_\_, Deputy  
DOCUMENT NO. \_\_\_\_\_

Statement of Evidence:

The northeast corner of Section 2, Township 36, Range 30, 4th Principal Meridian, Benton County, Minnesota, was set under the Public Land Survey as a post with bearing trees. No trace of post or trees now exists.

A search by Benton Co. Highway personnel of available county survey records revealed no additional information on this corner.

In 1995, Comstock & Davis, Inc., while remonumenting section corners for the purpose of G.P.S. work for Benton County found a 1-1/2 inch iron pipe at the northeast corner position of Section 2, Twp. 36, Rng. 30, Comstock & Davis, Inc. compared the location of the 1-1/2 inch iron pipe to the original U.S. Government survey and found the position to be within reason of the Public Land Survey records. Comstock & Davis, Inc. accepted the position of the 1-1/2 inch iron pipe as the position for the northeast corner of Section 2, refer to Job 945017.

2 3 0 3 1 5

OFFICE OF  
BENTON COUNTY RECORDER  
BENTON COUNTY, MN  
CERTIFIED TO BE FILED  
AUG 31 12 52 PM '95

AUG 31 12 52 PM '95

ALISE S. B. STEVENSON  
COUNTY CLERK  
BY Mm DEPUTY CM